

## New Product Announcement for May 2015

### BMW 5 Series (E60/E61)\* 2003-2007



Tail Lamp Unit  
**11-11983-21-9 RH**  
**11-11984-21-9 LH**  
 63210414700 RH + LH

Smoke


For Sedan

### CITROËN C3 (A51)\* 2009-2013



Outer Tail Lamp Unit  
**11-12453-01-2 RH**  
**11-12454-01-2 LH**  
 6351HZ / 6351KQ  
 6350HZ / 6350KQ  
 (not in 2015 Lighting catalogue)

### DACIA Logan (LS/KS/US/FS)\* 2004-



Cooling Fan Assembly  
**828-0002**  
 8200765566 / 6001548527 / 6001550562  
 Pull fan  
 2 pins  
 Replaces 828-1006, 380mm blade diameter,  
 320W, For engine code: K4M690/ K7M690/  
 K9K790/ K9K792/ K9K796

### DACIA Sandero (B90)\* 2008-




Cooling Fan Assembly  
**828-0002**  
 8200765566 / 6001548527 / 6001550562  
 Pull fan  
 2 pins  
 Replaces 828-1006,  
 380mm blade diameter, 320W,  
 For engine code: K9K792

### HYUNDAI Accent III (MC)\* 2005-2010



Mirror Glass  
**313-0049-1 RH**  
**313-0050-1 LH**  
 876211E000  
 876111E010  
 Convex glass

### HYUNDAI Accent III (MC)\* 2005-2010



Mirror Glass  
**313-0051-1 RH**  
**313-0052-1 LH**  
 876211E100  
 876111E110  
 Convex glass, With heater

### TOYOTA Auris (\_E18\_) \* 2012-



Fog Lamp Unit  
**19-12319-01-9 RH**  
**19-12320-01-9 LH**  
 81210-02110  
 81220-02110  
 H16

### TOYOTA Aygo (PAB4\_,KGB4\_) \* 2014-



Fog Lamp Unit  
**19-12319-01-9 RH**  
**19-12320-01-9 LH**  
 81210-02110  
 81220-02110  
 H16

### TOYOTA Yaris (P13)\* 2014-



Fog Lamp Unit  
**19-12319-01-9 RH**  
**19-12320-01-9 LH**  
 81210-02110  
 81220-02110  
 H16